
Agfa Corporation
200 Ballardvale Street
Wilmington, Ma 01887
Dkt#: XP-1108 Filed June 27, 2003
Titled: System And Method For Determining The Operational
Status Of An Imaging System Including An Illumination Modulator

1 Of 6



Agfa Corporation
200 Ballardvale Street
Wilmington, Ma 01887
Dkt#: XP-1108 Filed June 27, 2003
Titled: System And Method For Determining The Operational
Status Of An Imaging System Including An Illumination Modulator

2 Of 6





FIG.2

Agfa Corporation
200 Ballardvale Street
Wilmington, Ma 01887
Dkt#: XP-1108 Filed June 27, 2003
Titled: System And Method For Determining The Operational
Status Of An Imaging System Including An Illumination Modulator

3 Of 6






FIG.5A

Agfa Corporation 200 Ballardvale Street Wilmington, Ma 01887 Dkt#: XP-1108 Filed June 27, 2003

Titled: System And Method For Determining The Operational Status Of An Imaging System Including An Illumination Modulator




FIG.5B




FIG.5C